

Applications

Clean the surface thoroughly with water to remove dust / soil and any other loose particle from the surface.

Wipe out the water before application.

Wait for surface to dry.

Apply 1 to 2 coats(if required) with brush or spray uniformly
(Wait for at least 30 min. after each coat)

Surface is ready to use after 24 hours.

Note: The customer must verify the suitability of any information, opinion, recommendation or advice (“Information”) provided by the Company for the particular application for which any goods are intended to be used and the Company accepts no liability (whether in contract tort, or otherwise) whatsoever for any loss, damage, or expense arising from the misuse of any information it supplies nor for the use of any information in or for applications which are unsuitable or inappropriate. Nushar India Future Tech Pvt. Ltd. operates a continuous research and development programme and reserves the right to alter or update information from time to time.